

Ashgrove House
 26 Foxrock Court
 Dublin 18
 D18 R2K1

Mob. 086-3819011
 e-mail - thetreefile@eircom.net

Graphic Representation of Tree Form, balance and Protection Zone

Canopy Extent
 Cardinal Radii
 Category Code
 Stem Circumference

Root Protection Area (RPA)
 This area relates the "RPA" radius as defined in the Tree Survey Table and is measured from the tree centre.
 This area defines the preliminary Construction Exclusion Zone (CEZ) that must be protected by fencing from the potentially damaging effects of construction activity.


- Tree Quality (Categorisation)
- Category "A" Trees (Green Button)
Excellent Trees
 - Category "B" Trees (Blue Button)
Good Trees
 - Category "C" Trees (Gray Button)
Mediocre to Poor Trees
 - Category "U" Trees (Red Button)
Dead, Dying or Otherwise Compromised Trees that are Unstable.
- Tree Line
 Hedges
 Scrub and Thicket

Survey of Trees Within "Yellow Dashed" Zone Undertaken by and is Reproduced courtesy of "Arborist Associates". Refer to Arborist Associated Documentation for Full Text and Findings

- Colour Coding of Tree Protection Measures
- Location Of Primary Construction Exclusion Fencing
 - Area Of Primary Construction Exclusion Fencing
 - Location of known works within "Construction Exclusion Zone", to be undertaken using low-impact methodologies and under the guidance of the Project Arborist

- Colour Coding of Tree Retention or Removal
- Trees Intended for Retention - Solid Green Crown Outline
 - Trees Intended for Removal In Conjunction With Development Works - Broken Pink Crown Outline

Trees not located on topographical drawing have been given estimated locations



This Drawing Must Be Read in Conjunction with the Associated Arboricultural Report

Client: Fingal County Council
 Scale: 1:500 Date: March 2022
 Project: Tree Survey, Churchfields, Mulhuddart, Dublin 15
 Description: Tree Impacts and Protection Plan
 Drawing Title: Mulhuddart Tree Impacts and Protection Plan WEST